

Date:

22-02-2025

Report Type:

Maintenance

Customer:

Name: Center Sabot	Location: Sul -
--------------------	-----------------

Machine:

Name: motus Ax <input type="checkbox"/>	Type: Alex andrite
Model: M112 A1	Serial No.: -

Inspection:

Lamp shots: 2031527	Conductivity: 1.0 us
Rod shots: 11320594	Lenses: ok
Lamps No.: 4	Main shape: ok
Moveo use: 65 %	Water leak: ok
Photod.: External 45 J Internal 45 J	Electrical & Hydraulic parts: ok
Results (phtod. & peltier)%: 1.3 %	Power Before replacement: 23.5-540 After replacement: 30.6-497
Fiber test: ok	
Alarms: low energy	

Report:


low energy) more than 5 times

Actions:

change Flush lamp

Cost: \$1400

Engineer name & signature:



Customer Name & signature

