

Date:

21-03-2025

Report Type:

Maintenance

Customer:

Name: <i>Center Position</i>	Location: <i>S.L</i>
------------------------------	----------------------

Machine:

Name: <input type="checkbox"/>	Type:
Model:	Serial No.:

Inspection:

Lamp shots: <i>2163709</i>	Conductivity: <i>1.6</i>
Rod shots: <i>8265447</i>	Lenses: <i>OK</i>
Lamps No.: <i>4</i>	Main shape: <i>OK</i>
Moveo use: <i>OK</i>	Water leak: <i>OK</i>
Photod.: External - Internal	Electrical & Hydraulic parts: <i>OK</i>
Results (phtod. & peltier)%: <i>1.9 CG</i>	Power Before replacement: <i>-</i>
Fiber test: <i>OK</i>	Power After replacement: <i>-</i>
Alarms: <i>no Alarm</i>	

Report:


The fiber was born

Actions:


I change the fiber

Cost: *81800*

Engineer name & signature:



Customer Name & signature



Iraq (Erbil, Duhok, Sulaimanya, Kerkuk, Baghdad)

Main Office: Erbil, Mahmood Alhafeed Square