

Date:

2025/9/7

Report Type:

maintance

Customer:

Name: <u>Dr Shobaba Rasool</u>	Location: <u>gal</u>
--------------------------------	----------------------

Machine:

Name: <u>H. R</u> <input type="checkbox"/>	Type: <u>Alex</u>
Model: <u>Zenith v1</u>	Serial No.: <u>504-19-772-ZTHA</u>

Inspection:

Lamp shots: <u>1,055,767</u>	Conductivity: <u>-</u>
Rod shots: <u>4,222,866</u>	Lenses: <u>2</u>
Lamps No.: <u>-</u>	Main shape: <u>✓</u>
Moveo use: <u>-</u>	Water leak: <u>✓</u>
Photod.: External <u>-</u> Internal <u>-</u>	Electrical & Hydraulic parts: <u>✓</u>
Results (phtod. & peltier)%: <u>-</u>	Power
Fiber test: <u>✓</u>	Before replacement:
Alarms: <u>no Alarm</u>	After replacement:

Report: * low Energy
1 - there is spot on the Rod + internal lens (501-2000)

Actions:

1 - I change the flash lamp.
no warranty

Cost: \$ 2500

Engineer name & signature:

[Signature]

Customer Name & signature

[Signature]