

Date:

28-03-2026

Report Type:

Maintenance

Customer:

Name: Center Divia	Location: Sul
--------------------	---------------

Machine:

Name: M75 Ax 1	Type: Alexander
Model: M12A1	Serial No.:

Inspection:

Lamp shots: 1249,741	Conductivity: 3.1 uS
Rod shots: 6249,741	Lenses: on
Lamps No.: 1	Main shape: on
Moveo use: 79%	Water leak: on
Photod.: External 49% Internal 49%	Electrical & Hydraulic parts: on
Results (phtod. & peltier)%: 3.9%	Power
Fiber test: on	Before replacement: 27.8 = 545
Alarms: low energy	After replacement: 30.6 = 450

Report:


low energy more than 10 times

Actions:

I change flush lamp

Cost:

Engineer name & signature:



Iraq (Erbil, Duhok, Sulaimanya, Kerkuk, Baghdad)

Customer Name & signature



Main Office: Erbil, Mahmood Alhafeed Square