

Date:

30-01-2025

Report Type:

Maintenance

Customer:

Name: Dr. Birvan	Location: Koya
------------------	----------------

Machine:

Name: Hair Removal <input type="checkbox"/>	Type: Alex
Model: MIRA1	Serial No.:

Inspection:

Lamp shots: 5,959, 657	Conductivity: 8.8 us X
Rod shots: 46681434	Lenses: on
Lamps No.: 6	Main shape: on
Moveo use: 99 do	Water leak: on
Photod.: External 45 J Internal 45 J	Electrical & Hydraulic parts: on
Results (phtod. & peltier) %: 90.4	Power Before replacement: 30.6 = 549
Fiber test: on	Power After replacement: 30.6 = 501
Alarms: low charge	

Report:


Low Power

Actions:


I change flush lamp

Cost: 82000 $\xrightarrow{\text{dis}}$ 81500

Engineer name & signature:



Customer Name & signature



Iraq (Erbil, Duhok, Sulaimanya, Kerkuk, Baghdad)

Main Office: Erbil, Mahmood Alhafeed Square