

Date:

2025/3/26

Report Type:

maintenance

Customer:

Name: Dr. Laveen Othman	Location: Sul
-------------------------	---------------

Machine & Inspection:

Name	Type	Model	Serial Number	Lamp Shoots	✓/✗
H.P	Alex	Combi	ALT 2203004	105,802	✓

Report:

The fiber lens was damaged (H.P. side)

Actions:

I change the lens

Price:

\$200 ~~250~~ \$150

Engineer name & signature:

Customer Name & signature