

Date:

Report Type:

13-12-2024

Maintenance

Customer:

Name: Dr. Khalid Z	Location:
--------------------	-----------

Machine:

Name: motus AX 2	Type: Alex
Model: MIRA1	Serial No.:

Inspection:

Lamp shots: 992221	Conductivity: 0.748
Rod shots: 21617673	Lenses: on
Lamps No.: 10	Main shape: on
Moveo use: 0%	Water leak: on
Photod.: External 49 Internal 49	Electrical & Hydraulic parts: on
Results (phtod. & peltier)%: 0.6	Power
Fiber test: on	Before replacement: 30.65 545
Alarms: low energy	After replacement: 30.65 690

Report:

Power was low

Actions:

I change the flush lamp

Cost: \$ 1200

Engineer name & signature:

[Signature]

Customer Name & signature

[Signature]